

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	11/01/2018 11/01/2018	Bob Duffey

LM Start		Rating **	A	Issue No.	12
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0070_01_f_2015_12				
Comment Code					
Inspector Comment					
The LMA has the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	13
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0070_01_s_2013_13				
Comment Code					
Inspector Comment					
The LMA has adequate flood fight supplies and equipment.					

No Photos

LM Start		Rating **	A	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0070_01_s_2013_14				
Comment Code					
Inspector Comment					
The LMA completed flood fight training in 2016.					

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	11/01/2018 11/01/2018	Bob Duffey

LM Start	0.71	Rating **	M	Issue No.	41
LM End	0.78	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.144486 °	39.145602 °
				-121.842547 °	-121.842573 °
DWR ID	DWR_RD0070_01_f_2018_41				
Comment Code					
Inspector Comment					
2017 Site ID: BTS 0.8 R					
Status: Eroding New					
2017 Field Notes: Erosion along lower bank, one section has slumped off. Large cracks observed, and expecting additional slumping failures.					
Site History:					

No Photos

LM Start	0.76	Rating **	A/W	Issue No.	36
LM End	0.76	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.145240 °	39.145240 °
				-121.842650 °	-121.842650 °
DWR ID	DWR_RD0070_01_f_2017_36				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:154					
Site Designation:RD 70-03					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/17/2017					
Notes:					

Photo 1 of 3 : LEVAL_FA_2018_154_1686.jpg



* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	11/01/2018 11/01/2018	Bob Duffey


LM Start	0.76	Rating **	A/W	Issue No.	36 (cont)	
LM End	0.76	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.145240 °	39.145240 °	
				-121.842650 °	-121.842650 °	
DWR ID	DWR_RD0070_01_f_2017_36					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:154						
Site Designation:RD 70-03						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:7/17/2017						
Notes:						

LM Start	0.76	Rating **	A/W	Issue No.	36 (cont)
LM End	0.76	Issue Type +	Ma	Location *	

Photo 2 of 3 : LEVAL_FA_2018_154_1687.jpg



Photo 3 of 3 : LEVAL_FA_2018_154_1688.jpg



*** Location**
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Reclamation District No. 0070 Meridian

View of the rodent holes along the waterside slope.

View of no vegetation on both slopes.

View of the ruts along the waterside slope.

Page 4 of 6

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sutter Bypass	Right	7.92	11/01/2018 11/01/2018	Bob Duffey

LM Start	6.57	Rating **	U	Issue No.	40
LM End	6.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.192283 °	39.192283 °
				-121.914388 °	-121.914388 °
DWR ID	DWR_RD0070_01_f_2018_40				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : FA_2018_RD0070_29_40_20180905_00019.jpg



View of rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start		Rating **	C	Issue No.	82		
LM End		Issue Type +	Ma	Location *	WS		
Category	Supplemental			GPS Latitude/Longitude			
				Start		End	
Item	2017 USACE Erosion Survey, DRAFT				°		°
					°		°
DWR ID	DWR_RD0070_02_f_2018_82						
Comment Code							
Inspector Comment							
2017 Site ID: SAC 125.8 L							
Status: Repaired							
2017 Field Notes:							
Site History: 2005 - Site was repaired. 2009 - Site is at upstream end of the repair site. 2011 - Still minor erosion. 2012 - Site shortened to remove non-eroding section, minor erosion with failing cobbles. 2016 - Locals dumped rock and bank appears stable. Site removed.							

No Photos

LM Start	0.05	Rating **	M	Issue No.	84
LM End	0.32	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.193219 °	39.190038 °
				-121.935783 °	-121.934199 °
DWR ID	DWR_RD0070_02_f_2018_84				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 138.1 L					
Status: Eroding					
2017 Field Notes: No observed change.					
Site History: 1997 - Loss of cobble revetment in levee section. 2004 -					
New fresh erosion in a short section of the downstream end. 2010 -					
New deposition on cobbles. 2016 - Site appears to be stabilizing.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	0.07	Rating **	A/W	Issue No.	74
LM End		Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.193083 °	°
				-121.935258 °	°
DWR ID	DWR_RD0070_02_f_2017_74				
Comment Code					
Inspector Comment					
Levee Evaluation Comments Description: Site ID No:142 Site Designation:LMA-22 Repair Type: Erosion Rating:Area of Concern Field Date:6/7/2017 Notes: Problematic site was not found. No erosion observed. The erosion is down by the summer water line in the rocks. Continue monitoring the site.					

No Photos

LM Start	2.40	Rating **	M	Issue No.	49
LM End	2.40	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.165462 °	39.165462 °
				-121.935244 °	-121.935244 °
DWR ID	DWR_RD0070_02_f_2016_49				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	3.46	Rating **	C	Issue No.	76
LM End	3.46	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.155008 °	39.155008 °
				-121.921905 °	-121.921905 °
DWR ID	DWR_RD0070_02_f_2017_76				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
The rodent holes were repaired along the waterside slope.					

No Photos

LM Start	4.31	Rating **	M	Issue No.	51
LM End	4.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.144305 °	39.144305 °
				-121.917400 °	-121.917400 °
DWR ID	DWR_RD0070_02_f_2016_51				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	4.95	Rating **	M	Issue No.	54
LM End	4.95	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.142016 °	39.142016 °
				-121.926214 °	-121.926214 °
DWR ID	DWR_RD0070_02_f_2016_54				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : FA_2018_RD0070_30_54_20180905_00008.jpg



View of the trees blocking visibility.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	6.42	Rating **	M	Issue No.	83
LM End	6.54	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.132040 °	39.130900 °
				-121.936521 °	-121.934690 °
DWR ID	DWR_RD0070_02_f_2018_83				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 131.8 L					
Status: Eroding					
2017 Field Notes: Difficult to observe with excessive vegetation growth.					
Site History: 2005 - (known as 132) On inside of bend. Erosion of berm toe. Levee slope is steep. Erosion probably due to eddy scour off upstream cobble. 2009 - Groins may be a good option for repair.					
2010 - Scour off the upstream rock, some new erosion. 2011 - Site extended downstream. 2012 - Minor new erosion since last year and new animal holes. 2012 - Minor new erosion since last year and new animal holes. 2013 - New tree popout.					

No Photos

LM Start	7.74	Rating **	N	Issue No.	59
LM End	7.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.124503°	39.124503°
				-121.915252°	-121.915252°
DWR ID	DWR_RD0070_02_f_2016_59				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	8.10	Rating **	M	Issue No.	60
LM End	8.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.122568 °	39.122568 °
				-121.909723 °	-121.909723 °
DWR ID	DWR_RD0070_02_f_2016_60				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	9.28	Rating **	M	Issue No.	61
LM End	9.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.107285 °	39.107285 °
				-121.900753 °	-121.900753 °
DWR ID	DWR_RD0070_02_f_2016_61				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : FA_2018_RD0070_30_61_20180905_00012.jpg



View of the rodent holes along the landside slope.

LM Start	9.69	Rating **	N	Issue No.	63
LM End	9.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.101343 °	39.101343 °
				-121.899381 °	-121.899381 °
DWR ID	DWR_RD0070_02_f_2016_63				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	11.07	Rating **	C	Issue No.	48
LM End	11.07	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.086098 °	39.086098 °
				-121.889988 °	-121.889988 °
DWR ID	DWR_RD0070_02_s_2018_48				
Comment Code					
TR : Tree or limb					
Inspector Comment					
The tree was removed from the waterside slope and toe.					

No Photos

LM Start	13.82	Rating **	A/W	Issue No.	72
LM End	13.82	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.068370 °	39.068370 °
				-121.862763 °	-121.862763 °
DWR ID	DWR_RD0070_02_s_2017_72				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the erosion along the waterside slope.					

Photo 1 of 1 : FA_2018_RD0070_30_72_20180905_00016.jpg



View of the erosion along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	13.83	Rating **	A/W	Issue No.	75
LM End	13.83	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.068190 °	39.068190 °
				-121.862700 °	-121.862700 °
DWR ID	DWR_RD0070_02_f_2017_75				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:152					
Site Designation:RD 70-01					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/17/2017					
Notes: bank slope erosion around a drainage pipe/box					

LM Start	13.83	Rating **	A/W	Issue No.	75 (cont)
LM End	13.83	Issue Type +	Ma	Location *	

Photo 1 of 3 : LEVAL_FA_2018_152_1717.jpg



Photo 2 of 3 : LEVAL_FA_2018_152_1728.jpg

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	13.83	Rating **	A/W	Issue No.	75 (cont)
LM End	13.83	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 Storm Damage			39.068190°	39.068190°
				-121.862700°	-121.862700°
DWR ID	DWR_RD0070_02_f_2017_75				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:152					
Site Designation:RD 70-01					
Repair Type: Erosion					
Rating:Area of Concern					
Field Date:7/17/2017					
Notes: bank slope erosion around a drainage pipe/box					

Photo 3 of 3 : LEVAL_FA_2018_152_1730.jpg



LM Start	14.08	Rating **	M	Issue No.	81
LM End	14.21	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.069166°	39.070105°
				-121.857995°	-121.855929°
DWR ID	DWR_RD0070_02_f_2018_81				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 123.3 L					
Status: Eroding					
2017 Field Notes: minor new erosion. additional tree popout.					
Site History: 2006 - Erosion into the levee toe. Rock at upstream end has poor transition causing eddy scour. 2010 - Minor new erosion.					
2011 - Some fresh erosion. 2012 - Additional slumping on the previously slumped bank, site extended downstream.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Reclamation District No. 0070 Meridian

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento River	Left	15.50	11/01/2018 11/01/2018	Bob Duffey

LM Start	15.11	Rating **	A	Issue No.	55
LM End	15.11	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.067052°	39.067052°
				-121.842738°	-121.842738°
DWR ID	DWR_RD0070_02_f_2018_55				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
There was no vegetation on both slopes.					

Photo 1 of 1 : FA_2018_RD0070_30_55_20181102_00127.jpg



View of no vegetation on both slopes.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---